

This case history is of a vertical gas and water well, producing high volume gas with less than 200bbl/day of water. RECON's HDPLT measurements allowed us to overlay the three fluid ID sensors (density, capacitance and holdup) in order to confirm at what intervals the water was entering the wellbore. This allowed for easy remediation initiatives to be developed by the Operator.

